





Date



P.O. Box 4942, Baltimore, Maryland 21220  
Phone: (410) 574-4144 / Fax: (410) 760-4439

yes,  
actions.

<b>Propeller Log Entry</b>		<b>Hobbs:</b>	<b>542.4</b>	<b>Registration #:</b>	<b>N45FF</b>
<b>Date:</b>	<b>December 1, 2008</b>	<b>Total Time:</b>	<b>542.4</b>	<b>Make/Model:</b>	<b>HC-E4N-3Q</b>
<b>W/O:</b>	<b>25664</b>	<b>Cycles:</b>	<b>603</b>	<b>S/N:</b>	<b>HH2407</b>
		<b>TSO:</b>			

**Performed a 100-HOUR inspection:**

- Performed an annual/100 hour inspection of the propeller per the Piper PA-46-500TP Malibu/Meridian MM Ch. 5-20-00.

**Complied with the following Special Inspections per Chapter 05-30-00:**

- Performed a 6 month/12 month/400 hour propeller lubrication per the Piper PA-46-500TP Malibu/Meridian MM chapter 12-20-00 and Hartzell Propeller Owner's Manual # 149, 61-00-49 pages 6-5 to 6-7.

**Complied with the following Airworthiness Directives (AD's):**

- Performed AD 2008-13-26 To Prevent Failure of the Propeller Hub by excluding propeller from applicability paragraph (c) as propeller is not left-hand rotating. No further action needed. Effective date of the AD is July 17, 2008.
- AD notes checked thru bi-weekly 2008-23. See AD log dated November 11, 2008.

**Complied with the following Service Bulletins (SB's):**

- Performed Piper VSP 161 Hartzell HC-SL-61-254 Propeller Operating Restrictions by performing ground run up to determine if engine/propeller rigging permits operation below

10 = 2



P.O. Box 4942, Baltimore, Maryland 21220  
Phone: (410) 574-4144 / Fax: (410) 760-4439

minimum idle of 1200 RPM IAW HC-SL-61-254 accomplishment instructions 2(c)(1). NDN. No further compliance needed. Effective date of the VSP is March 20, 2007.

**Completed the following additional items:**

- Profiled small nicks from leading edges of propeller blades and painted as needed.
- Cleaned and polished propeller deice slings using LPS electrical contact cleaner.
- Repaired cul deice boot using FR1422B1/2 PRC and bonded leading edge corners using 3M 1300 scotch-grip.
- Installed .032 safety wire on propeller attach nuts IAW Piper PA-46-500TP MM Chapter 61-10-00.
- Installed chafe tape p/n 3M-361 to shim spinner dome support.

I certify that this **PROPELLER** has been inspected in accordance with a **100-HOUR** inspection and was determined to be in airworthy condition.

**MAINTENANCE RELEASE**

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency under **Work Order No: 25664 Date: December 1, 2008**

Signed \_\_\_\_\_ for Skytech, Inc., P.O. Box 4942, Baltimore, MD 21220. CRS# LF1R294K

2 = 2





