

SALES ORDER: 148238
ENGINE S/N: RM0261
ENGINE MODEL: PT6A-42A

ENGINE LOGBOOK

PT6A TURBOPROP ENGINE

PCE-RM0261

A/C SN: 4697241



PRATT & WHITNEY CANADA



Delivery Note

Page 1

No. 81092257

Date 2007.10.22

COPY

P&WC JE3-6978-E (2004-07)

Ship to

Flightline Group
3256 Capital Circle SW
TALLAHASSEE FL 32310
USA

Reference number
Customer number 25875
Freight forwarder
Waybill number 81092257 MILLER & SONS
IRS 47-8012168758-9

Sales Representative William D Boyles

Shipping Conditions

Standard

Information

lip x 1387

BILL SALES ORDER: 148238 ENGINE S/N:RM0261

SHIP — HOT SHOT

POC: FRED DAVIS
PHONE: 850-576-3515
SHIPPING ADDRESS
FLIGHTLINE GROUP INC.
3256 CAPITAL CIRCLE SW
TALLAHASSEE, FL 32310

SEND HEPWORTH SURVEY TO: Ted Spicer
E-MAIL ADDRESS: tedspicer@cayclubs.com

Delivery Details

Item	Material Description	Quantity
0001	BS1192 PT6A-42A Customer Material No. / Item 000000 Batch no. RM0261 RM0261	1 EA

Packing List

Page 1

No. 81092257

Date 2007.10.22

P&W: 483 8370 E (2002-31)

GST 101 1030665 70 0005M - GST R100071000

Packing Information

Ship To

Flightline Group
3256 Capital Circle SW
TALLAHASSEE FL 32310
USA

Forwarding Agent

Waybill No.



81092257 MILLER & SONS

Incoterms FCA PWES - Bridgeport

Shipping Instructions

11p x 1387

BILL SALES ORDER: 148238 ENGINE S/N/RMD261

SHIP --- HOT SHOT

POC: FRED DAVIS
PHONE: 850-576-3515

SHIPPING ADDRESS
FLIGHTLINE GROUP INC.
3256 CAPITAL CIRCLE SW
TALLAHASSEE, FL 32310

SEND HEPWORTH SURVEY TO: Ted Spicer
E-MAIL ADDRESS: tedspicer@cayclubs.com

Packing List

Page 2

No. 81092257

Date 2007.10.22

ISSUE: JRS (REV) E (0003-10)

GST US 1626165 TO 0000MS - GST BRIDGEPORT

Packing information

Ship To

Flightline Group
3256 Capital Circle SW
TALLAHASSEE, FL 32310
USA

Forwarding Agent

Waybill No.



81092257 MILLER & SONS

Incoterms FCA PWES - Bridgeport

Shipping Unit 1100185

Shipping Unit No.



1100185

Length



81

Total Weight



740

Width



29

Height



33

UCM



LB

Volume



1.208

Item 000001 / 1100185

Item No.

000001

Material No.



BS1192

PT6A-42A

Purchase Order No.



07-0801

Description

Country of Origin

Quantity



1.00

Sales Order No.



148238



Pratt & Whitney

A United Technologies Company

Pratt & Whitney Engine Services, Inc.
1825 Midway Park Road
Bridgeport, WV 26330

Waybill Recap Sheet

Page 1

No.



Date 2007.10.22

PAWC JRS-5880-E (2003-10)

QST 100 1620168 TQ 0005MF - GST R104287008

Shipping Information

Ship to

Flightline Group
3256 Capital Circle SW
TALLAHASSEE FL 32310
USA

Forwarding Agent Name

Waybill number 81092257 MILLER & SONS

Customer Broker

Shipping Conditions 01

Incoterms FCA
PWES - Bridgeport

IRS 47-8012168758-9

Customer Account Number

Value for Customs see attached Customs Invoice

Shipping notes

1lp x 1387

BILL SALES ORDER: 148236 ENGINE S/N:RM0261

SHIP --- HOT SHOT

POC: FRED DAVIS
PHONE: 850-576-3515
SHIPPING ADDRESS
FLIGHTLINE GROUP INC.
3256 CAPITAL CIRCLE SW
TALLAHASSEE, FL 32310

SEND HEPWORTH SURVEY TO: Ted Spicer
E-MAIL ADDRESS: tedspicer@cayclubis.com

Delivery Details

Shipping Unit Number	Length	Width	Height	Volume	Weight (KG)
100185	81	29	33	1.208	740
Total Number of Shipping Units 00001				1.208M3	740.00KG

2007-10-22 13:17:05 RS 2007.10.22 13:18:34 PR1 400 PR1

http://uniqueusa/imp/pt81AD1022131705E

End-of-document



To: Tiffin Aire Inc.

Subject: 8130-3 Correction
Customer PO 715198WN
IGS Work Order 2110767
Honeywell Fuel Control 4138014-1, Serial C82076

From: Nathan Long, Chief Inspector


To whom it may concern,

During a routine audit of completed work packages it was noted that Honeywell Service Bulletin, 4138014-73-2R1 was inadvertently omitted from the 8130-3. SB# 4138014-73-2R1 covers the inspection and or replacement of the bi-metallic lever. The above-mentioned SB was complied with, it just was not documented on the 8130-3. I want the records to be accurate, so I have generated a revised 8130-3.

Please feel free to contact me if you have any questions.

Thanks for your business.

Nathan Long, Chief Inspector
International Governor Services, LLC
FAA Repair Station IG0R976N
EASA Approval 145.4575
(303) 464-0043 Phone
(303) 464-0044 Fax
Toll Free: 1-888-808-5297
nathan.long@internationalgovernor.com
www.internationalgovernor.com

 StandardAero		PT6A Series Borescope Report			
Customer: Cutter Aviation-Dallas		Work Order #: 40-01362	Order/Task: 232/383	Date: 09/14/20	Tech: Nate Sedore
Model: PT6A-42A	Serial: PCE-RM0261	TSN: 1143.9	CSN: 972	TSO: N/A	CSO: N/A

Engine Installation and Condition on Arrival:

Installed on N45FF.

INSPECTION POINT:	FINDINGS:
Inlet and First Stage Blades:	Nicks on 1 st Stage Blades. See additional information.
Combustion Liner:	Cracks and burn through on cooling ring. See additional information.
Small Exit Duct:	No defects.
CT Vane Ring:	Coating loss on leading edge of airfoil. See additional information.
CT Blades:	Suspected sulfidation on CT Blades. See additional information.
CT Segments:	No defects.
Second Stage PT:	No defects.
Exhaust Duct:	No defects.

GENERAL INSPECTION:	FINDINGS:
External Visual:	N/A
State of Preservation:	N/A

Additional Information:

1st Stage Blades: Nicks require blending.
Combustion Liner: Cracks and burn through on cooling ring. HSI is recommended.
CT Vane Ring: Coating loss on leading edge of airfoil. No action required.
CT Blades: Suspected sulfidation on CT Blades, recommend turbine wash and re-inspect to see if sulfidation is present.

